

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R128M - BASE LAYER SOFT SHELL JACKET

22.02.2016

| | XS | S | M | L | XL | 2XL | 3XL |
|----------------------------|-------|-------|--------|--------|--------|--------|-----|
| Full chest in inches* | 34 | 38 | 41 | 44 | 46 | 48 | 50 |
| Full chest in cm* | 86,36 | 96,52 | 104,14 | 111,76 | 116,84 | 121,92 | 127 |
| German clothing size (men) | 44 | 48 | 50 | 54 | 56 | 58 | 60 |

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm