TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R216X - HIGH VIZ WATERPROOF SUIT

24.02.2016

	XS	S	М	L	XL	2XL	3XL	4XL
JACKET								
Full chest in inches*	36	38	41	44	47	50	53	56
German clothing size (men)	46	48	50	54	56	60	64	66
TROUSERS								
Inside leg in inch	27,5	29	30	31	31,5	32	32	32
Inside leg in cm	72	74	76	79	80	81	81	81

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm